EVN Performance and Reliability

Jay Blanchard EVN TOG Meeting, St. Petersburg 2016





• N16L2:

- JB subband 5 LCP (BBC11:Lower) systematically low amplitude.
- EF stopped observations at 13:02 due to a calibration script which overwrote the schedule.
- T6 lost scans 1 and 2, required DBBC reset.
- TR low amplitude in both pols for baseband 8 (BBC 04:Upper and 08:Upper). Poor subband 1 LCP.
- SR missed first two hours due to electrical room upgrade.

• N16C2:

- WB recorder linear polarisations due to broken hybrid.
- NT saw tooth shaped bandpass in LCP.
- TR LCP subband 2 systematically low power
- T6 disks delayed due to customs issue.
- IR crossed pols.
- MC dip in bandpass subbands 5 and 7 RCP/LCP.

• N16M2:

- MC dip in bandpass subbands 5 and 7 RCP/LCP.


- EF crossed pols, fixed by scan 2.
- UR did not participate due to problem with receiver.

jops@eee Tue-29-Nov-2016/17:57:

data: n1612.ms page:8/12

Pol=RR LL RL LR; Nsub=8

 ${\tt Scalar-averaged~26-May-2016/11:02:00->11:03:00;~Weight=0.7}$



• N16L2:

- JB subband 5 LCP (BBC11:Lower) systematically low amplitude.
- EF stopped observations at 13:02 due to a calibration script which overwrote the schedule.
- T6 lost scans 1 and 2, required DBBC reset.
- TR low amplitude in both pols for baseband 8 (BBC 04:Upper and 08:Upper). Poor subband 1 LCP.
- SR missed first two hours due to electrical room upgrade.

• N16C2:

- WB recorder linear polarisations due to broken hybrid.
- NT saw tooth shaped bandpass in LCP.
- TR LCP subband 2 systematically low power
- T6 disks delayed due to customs issue.
- IR crossed pols.
- MC dip in bandpass subbands 5 and 7 RCP/LCP.

• N16M2:


- MC dip in bandpass subbands 5 and 7 RCP/LCP.

- EF crossed pols, fixed by scan 2.
- UR did not participate due to problem with receiver.

 $jops@eee\ Mon-05-Sep-2016/10:46:$

data: n16c2.ms page:5/11

Scalar-averaged 30-May-2016/14:57:00->14:58:00; Weight=0.7



• N16L2:

- JB subband 5 LCP (BBC11:Lower) systematically low amplitude.
- EF stopped observations at 13:02 due to a calibration script which overwrote the schedule.
- T6 lost scans 1 and 2, required DBBC reset.
- TR low amplitude in both pols for baseband 8 (BBC 04:Upper and 08:Upper). Poor subband 1 LCP.
- SR missed first two hours due to electrical room upgrade.


• N16C2:

- WB recorder linear polarisations due to broken hybrid.
- NT saw tooth shaped bandpass in LCP.
- TR LCP subband 2 systematically low power
- T6 disks delayed due to customs issue.
- IR crossed pols.
- MC dip in bandpass subbands 5 and 7 RCP/LCP.

• N16M2:

- MC dip in bandpass subbands 5 and 7 RCP/LCP.

- EF crossed pols, fixed by scan 2.
- UR did not participate due to problem with receiver.



• N16L2:

- JB subband 5 LCP (BBC11:Lower) systematically low amplitude.
- EF stopped observations at 13:02 due to a calibration script which overwrote the schedule.
- T6 lost scans 1 and 2, required DBBC reset.
- TR low amplitude in both pols for baseband 8 (BBC 04:Upper and 08:Upper). Poor subband 1 LCP.
- SR missed first two hours due to electrical room upgrade.

• N16C2:

- WB recorder linear polarisations due to broken hybrid.
- NT saw tooth shaped bandpass in LCP.
- TR LCP subband 2 systematically low power
- T6 disks delayed due to customs issue.
- IR crossed pols.
- MC dip in bandpass subbands 5 and 7 RCP/LCP.

• N16M2:


- MC dip in bandpass subbands 5 and 7 RCP/LCP.

- EF crossed pols, fixed by scan 2.
- UR did not participate due to problem with receiver.

jops@eee Thu-15-Dec-2016/17:22:

data: n16m2.ms page:4/9

Scalar-averaged 03-Jun-2016/12:02:00->12:03:00; Weight=0.7



2016 Session 2 June Feedback

General:

- Noto several times had RCP at half power of LCP.
- Torun BBC5:Upper had a different delay (phase vs freq) for all experiments this session.

• 6 cm:

- Westerbork broken hybrid no good circular pols.
- Several telescopes reported FS crashes.

• 1.3 cm:


- Urumqi receiver failure.
- Effelsberg swapped pols.
- Several telescopes (Hh, Ef, Sr, O8) reported issues with v105E firmware giving bad tsys and bit statistics.

jops @ eee~Thu-15-Dee-2016/17:22:

data: n18m2.ms page:4/8

Pol=RR LL RL LR; Nsub=8

Vector-averaged 03-Jun-2016/12:02:00->12:03:00; Weight=0.7



2016 Session 2 June Feedback

General:

- Noto several times had RCP at half power of LCP.
- Torun BBC5:Upper had a different delay (phase vs freq) for all experiments this session.

• 6 cm:

- Westerbork broken hybrid no good circular pols.
- Several telescopes reported FS crashes.

• 1.3 cm:

- Urumqi receiver failure.
- Effelsberg swapped pols.
- Several telescopes (Hh, Ef, Sr, O8) reported issues with v105E firmware giving bad tsys and bit statistics.

EZ025


jops@eee Thu-01-Dec-2016/18:31:

data: ez025.ms

Pol=RR LL; Nsub=8

page:6/8

Vector-averaged 31-May-2016/08:02:42->08:03:42; Weight=0.7



ш

2016 Session 3 Oct NME Results

N16L3:

- EF stayed on first target source (did not slew to second or third) thus missed the later parts.
- O8 could not participate due to strong winds.
- UR undergoing repairs did not participate.
- MERLIN: Data recorded for Cm, Kn, De often had reasonable sample stats but no fringes acheived.

• N16C3:

- JB appears to have been in the wrong MK5 mode all experiment. Initially in mk5b mode=ext,0x,,16.00 then VDIF 800-512-16-2 then mk5b mode=ext,0x,,32.0.
- UR broken receiver.
- MERLIN no fringes.
- IR time offset when transferring data, forcing manual selection of data 11 seconds from expected. Packet loss?

2016 Session 3 Oct NME Results

N16M3:

- KM Fringes but only for one scan with high rate → maser problem.
- IR subband 5 shows a dip in the center of the band.
- MERLIN stations no fringes, VDIF looks mangled.

• N16X1:

UR could not observe to to antenna drive motor failure.


N16K2:

- Nt mechanical disk failure.
- UR bad weather → no fringes in FTP but found on disk.

jops@eee Thu-23-Mar-2017/15:47: data: n16m3.ms

page:11/11

 ${\tt Scalar-averaged~20-0ct-2016/15:52:30->15:53:30;~Weight=0.7}$



2016 Session 3 Oct NME Results

N16M3:

- KM Fringes but only for one scan with high rate → maser problem.
- IR subband 5 shows a dip in the center of the band.
- MERLIN stations no fringes, VDIF looks mangled.

• N16X1:

UR could not observe to to antenna drive motor failure.

N16K2:

- Nt mechanical disk failure.
- UR bad weather → no fringes in FTP but found on disk.

General:

 Whole session after initial two 5 cm observations ran with DBBC firmware v105E.

- Irbene:

- Appears to have large packet loss to recorder.
- The first disk-pack proved unusable.
- Sub-band 5 (BBC 5,13 LSB) had a dip in the center of the band.
- Urumqi antenna gear-box maintenance → K band only.
- No fringes to MERLIN stations.
- Kunming (not yet "EVN") fringes in 6 cm, 5 cm,
 3.6 cm NMEs. Maser problem in 5cm NME.

• 5 cm:

 Effelsberg had broken amplifier in LCP for NME, fixed by the immediately following C-band session.

• 6 cm:

- Hartebeesthoek had a warm receiver in ER045A (cryo failure); also HA encoder jumping intermittently (but not a large problem).
- O8 EP099A left pointing offset in pointing model
 → weak fringes.
- Jodrell Bank no fringes in EM121B and EP099A:
 - 1 Gbps observations immediately following 2 Gbps observations.
 - Subsequent 2 and 1 Gbps observations were fine.

• 6 cm:

- Noto showed its typical falling-off in amplitude in the upper LCP channels (BBCs 13,15 in DBBC firmware v105E, but this has also occurred the "normal" firmware in which it was BBCs 7,8).
- Torun had an issue with a pack. Record-pointer went back to zero → 4.5 experiments lost in C and L band.
- Yebes receiver fault in ER045A (fixed during experiment).
- Zelenchukskaya had consistently low power in RCP channels throughout, and a warm receiver in EM126A.
- Robledo used new version of DVP back-end → no fringes in any observation.
 - Correlating single channel against all others showed some in the wrong place, but with 90 degree phase jump and null amplitude in the middle of the band.

• 18/21 cm:

- Irbene had an NTP error in EM123B that prevented recording.
- Jodrell bank fringe 'walked away' in jumps of 512 lags every 10-14 seconds.

• 1.3 cm:

- Noto cryo failure during NME.
- KVN Yonsei did not participate due to realignment of antenna panels.
- KVN Tamna had a hexapod failure in EP099B.

• 3.5 cm:

Noto had mark5 problems in EP099C.